ANNEXURE-III SCHOOL SANITARY CERTIFICATE Under Tamil Nadu Educational / Rules

(Chapter III Rule 24 and Appendix – E)

I hereby declare that I have inspected **Linga Global School Krishnankoil,Watrap Taluk, Virudhunagar District,** building and premises on the day of 20.01.2022 and certify.

- 1. That the accommodation provided for each of the several classes is sufficient for the minimum number of pupils there in and is properly ventilated and lighted.
 - 2. That the building is maintained in substantial repair.
- 3. That the latrine arrangements are adequate and maintained satisfactory and also kept clean and maintain with the bleaching powder and phenoil.
 - 4. That the supply of drinking water is wholesome, and that in all other necessary aspects the sanitation is good.
 - 5. Drinking water source should be chlorinated daily.
 - 6 .Adequate fire precautionary measures should be provided.
 - 7 .Adequate Emergency Exit should be provided.
 - 8. Rain water harvest structure must be provided in the premises.
- 9 .The water tanks (sintex/cement tank)in the campus should be kept clean by protecting it from mosquitoes, the wastages like plastic items, broken bottles and unused tyres should be replaced immediately from the rain water. Check every time whether the rain water staged in the terrace.
- 10. In School/College campus display of sign boards of size 60x30 cm(No Smoking area- smoking here is an offence) inside the instituition.
- 11. In School/College campus no sale of tobacco in the radius of 100 yards in educational instituitions.
- 12. Conditions to be followed as per R.No: 86684/EPI/S1/2020 dated 07.11.2020(Instructions of the chief secretary meeting regarding SOP of school reopening held on 05/11/2020)
- 13. Proper cleaning and sanitization should done at the school premises frequently and it should be recorded in a register.
 - 14. Hand sanitizers should be available in each classroom.
 - 15. The entire pupils in the school should be screened by IR Thermal scanner daily.
- 16. That essentials such as sanitizer, thermal scanner, disinfectants should available in the premises sufficiently.